

Company: Borucao Ingeniería & Arquitectura
Contact: Ing Gloriana Ouellette
Phone: 85797171
Email: glorianao@borucao.com

Title: 03/03/2026
Group: Tanque de Asada - Reparación
Created: Tue, 3/3/2026
No. Items: 5

(1)



Maxistick + Maxipatch

Created: Tue, 3/3/2026

Colocacion de maxistick en las fisuras de 0.5cm y colocacion de 0.5cm de espesor en paredes externas



Company: Borucao Ingeniería & Arquitectura
Contact: Ing Gloriana Ouellette
Phone: 85797171
Email: glorianao@borucao.com

Title: 03/03/2026
Group: Tanque de Asada - Reparación
Created: Tue, 3/3/2026
No. Items: 5

(2)



Maxistick + Maxipatch

Created: Tue, 3/3/2026



Company: Borucao Ingeniería & Arquitectura
Contact: Ing Gloriana Ouellette
Phone: 85797171
Email: glorianao@borucao.com

Title: 03/03/2026
Group: Tanque de Asada - Reparación
Created: Tue, 3/3/2026
No. Items: 5

(3)



Maxistick + Maxipatch

Created: Tue, 3/3/2026



Company: Borucao Ingeniería & Arquitectura
Contact: Ing Gloriana Ouellette
Phone: 85797171
Email: glorianao@borucao.com

Title: 03/03/2026
Group: Tanque de Asada - Reparación
Created: Tue, 3/3/2026
No. Items: 5

(4)



Maxistick + Maxipatch

Created: Tue, 3/3/2026



Company: Borucao Ingeniería & Arquitectura
Contact: Ing Gloriana Ouellette
Phone: 85797171
Email: glorianao@borucao.com

Title: 03/03/2026
Group: Tanque de Asada - Reparación
Created: Tue, 3/3/2026
No. Items: 5

(5)



Maxistick + Maxipatch

Created: Tue, 3/3/2026

